

# **Mechanical Face Drivers**

### **TYPE 45**

**Driving Diameter Range: 1.34" - 1.73"** 



### **Selecting the Face Driver components:**

- #1 Determine the Face Driver model with the type of mounting required for the machine.
- #2 If mounting directly to machine spindle, verify spindle size and select appropriate spindle adapter.
- #3 Choose the center point with the diameter range closest to the center hole diameter.
- **#4** Determine machine spindle rotation and driving diameter to select the correct drive pins. Rotation is determined by looking directly at the spindle face or chuck face. (For detailed instructions on selecting a face driver, see page 42).

# Mounting Styles Available for Type 45



#1 FACE DRIVER				
Order Code	Mounting Style			
4504	#4 Morse Taper*			
4505	#5 Morse Taper*			
45FM	Flange Mount*			

<sup>\*</sup> All mechanical styles can be chucked.

#2 SPINDLE ADAPTER (For direct mount only)						
Order Code	Spindle Size					
708037	A2-5					
708038	A2-6					
708039	A2-8					
708040	A2-11					

#### Morse Taper\*



Flange Mount\*

- \* All mechanical styles can be chucked.
- **TO ORDER:** A complete unit consists of a face driver, center point and drive pins. For direct mounts, a spindle adapter must be added.
- #1 Face Driver order code: \_ \_ \_ \_
- #2 Spindle Adapter
  order code: \_ \_ \_ \_ \_
  (only required for direct mount)
- #3 Center Point order code: \_ \_ \_ \_
- #4 Drive Pins
  order code: \_ \_ \_ \_ \_
  (6 pins required)

51

## #3 CENTER POINT #4 DRIVE PINS (6 pins required)

Order Code	Center Hole Dia. Range	Order Code	Counterclockwise (Right)		Clockwise (Left)	
			Outer Driving Diameter	Inner Driving Diameter	Outer Driving Diameter	Inner Driving Diameter
		P4501	1.34	0.95	_	_
		P4502	_	_	1.34	0.95
	0.08 - 0.710 0.669 - 0.866	P4503	1.54	0.95	_	_
		P4504	_	_	1.54	0.95
		P4505	1.73	0.95	_	_
		P4506	_	_	1.73	0.95
C4503		P4531	1.34	1.07	_	_
		P4532	_	_	1.34	1.07
	0.828 - 1.024	P4533	1.54	1.07	_	_
		P4534	_	_	1.54	1.07
		P4535	1.73	1.07	_	_
		P4536	_	_	1.73	1.07
C4504	0.984 - 1.181	P4541	1.34	1.22	_	_
		P4542	_	_	1.34	1.22
		P4543	1.54	1.22	_	_
		P4544	_	_	1.54	1.22
		P4545	1.73	1.22	_	_
		P4546	_	_	1.73	1.22
C4505	1.142 - 1.339	P4553	1.54	1.38	_	_
		P4554	_	_	1.54	1.38
		P4555	1.73	1.38	_	_
		P4556	_	_	1.73	1.38
C4506	1.299 - 1.496	P4565	1.73	1.54	_	_
		P4566	_	_	1.73	1.54

Call 1-800-338-0027

Working-TextCS6.indd 51 12/27/12 1:41 PM